

|                         |                  |
|-------------------------|------------------|
| FB 7-99                 | Revision 2015/45 |
| <b>Test CERTIFICATE</b> | Page 1 of 1      |

**Customer:**           xxx  
                          xxx  
                          xxx  
                          xxx

**Certificate No.**     123456

**P.O. No.:**           2562/ 19.05.2016

**Goods:**            MFM 10-1, Sheath testing/fault location unit 10kV

**S./No.:**            12020100001

**Our Ref. No.:**     123456

**Date:**             21.06.2016

The a.m. instruments have been adjusted and inspected to meet the specifications as published in the Operating Manual or as listed in our inspection sheet / test log.

We herewith confirm that the instruments being supplied by us are in full conformity with our technical specification. All measurements are traceable to national and international standards.

Our quality system complies with the standard norm: DIN ISO 9001:2008

Production

Quality assurance